



# Dana<sup>®</sup> Spicer<sup>®</sup> Axles & Brakes

## ABIB-9607


### Component Change for D461/521/581/601/651/652 Series Axles.

Effective September 21, 1994 the following component change took place on the above models. Bushings are no longer used in the end of the output shaft. The chart below identifies the old style part numbers and the current design part numbers related to this change, both old and new parts are inter-changeable with each other.

**NOTE:** When servicing these models, be sure to identify the output shaft by part number before attempting to install a bushing. Do not install a bushing onto the 129016 output shaft.

Service Kit Part No.	Description	Old Design Shaft Part No.	Part Number Of New Shafts
122418	Input Shaft Kit	119990	129017
122419	Output Shaft Kit	119991*	129016

\*Sub-assembly part number was 126168, (stamp # 119991, bushing part number is 48922)



---

# Roadranger®

**MORE TIME ON THE ROAD.**

For spec'ing or service assistance, call 1-800-826-HELP (4357) 24 hours a day, 7 days a week,  
(Mexico: 8-332-1515). Or visit our web site at: <http://www.roadranger.com> <http://www.roadranger.com>

ABIB-9607  
Printed in U.S.A.

Copyright Dana Corporation, 2001  
All Rights Reserved.  
[www.dana.com/heavytruck](http://www.dana.com/heavytruck)

Dana Corporation  
**Spicer Heavy Axle & Brake Division**  
P.O. Box 4097  
Kalamazoo, MI 49003