


G.M.C. — CHEVROLET

TWO-SPEED T150 — T170 — T185



2P-9

ILL. NO.	DESCRIPTION	PART NO.
1	Nut, Flange	3874317
4	Seal, Pinion	712598
5	Bearing, Pinion Shaft Cone	HM804848
6	Bearing, Pinion Shaft Cup	HM804810
9	Retainer, Pinion Cage	3874302 ✓
10	Shim, Pinion Retainer	
10	.006 Thick	3874307
10	.009 Thick	3874308
10	.015 Thick	3874310 ✓
10	.021 Thick	3874312 ✓
11	Spacer, Pinion Shaft Bearing	3874305 ✓
12	Bearing, Pinion Shaft Cup	55437
13	Bearing, Pinion Shaft Cone	55200C
14	Gear, Ring Gear and Pinion	
14	5.83 Ratio	3886301 ✓
14	6.50 Ratio	3886305 ✓
14	5.57 Ratio	3886300 ✓
14	7.17 Ratio	3886303 ✓
15	Bearing, Pinion Shaft Pilot	M5305TV
21	Shaft, Axle Shift	3880971 ✓
22	Carrier, Differential	3873550
31	Anchor, Axle Shift Fork Sleeve	3874327 ✓
32	Pin, Axle Shift Fork Dowel	3873555
33	Fork, Shift	3874325 ✓
34	Sleeve, Axle Shift Fork	3874345 ✓
35	Nut, Differential Bearing Adjuster LH	3892143 ✓
36	Bearing, Differential Cup	33472
37	Bearing, Differential Cone	33287
38	Bolt, Drive Gear	3874347 ✓
40	Case, Shift Half Side	3886315 ✓

**G.M.C. CHEVROLET
TWO SPEED
T150 — T170 — T185**

ILL. NO.	DESCRIPTION	PART NO.
40	Case, Shift Half and Drum Half	3886315 ✓
41	Gear, Sliding Clutch	3873578 ✓
42	Pinion, Idler	3873581 ✓
43	Case, Inner Differential Both Halves	3886317 ✓
44	Washer, Thrust	3860194 ✓
45	Gear, Differential Side	3873576 ✓
45	LH T150, T170	3873577 ✓
45	RH T150, T170	359359 ✓
45	LH T185	359360 ✓
45	RH T185	359360 ✓
46	Pinion, Differential	3873574 ✓
47	Washer, Thrust	3873575 ✓
48	Spider, Differential	3873573 ✓ → 3860196
51	Bearing, Differential Cone	42381
52	Bearing, Differential Cup	42584
53	Adjuster, Differential Bearing	3873584
54	Dowel, Differential Bearing Cap	3652274
57	Bolt, Differential Bearing Cap	3873554
58	Lock, Differential Bearing Adjuster	
58	RH	3702249
58	LH	3705837
58	Kit, Bearing, Gasket & Seals	RA170

122000
40635

Shift Kit
Motor



Reuse housing +
use parts to repair.

If housing is broken
must find used housing