

HAXL-PNI-017

# GENUINE SPICER® BEARING CUP & CONE CHANGES IN D170/D190 FAMILY AXLES

# PART NUMBER INFORMATION

DATE: 06/8/2012

TO: All Dana Aftermarket Group Spicer® Heavy Axle Customers

#### Affected Models: D/R170, D/R190, D/R590, S170, S190, S590

In order to meet more demanding application and performance expectations, Dana is pleased to announce a product design change in the models listed above. Dana began implementing the use of the new design, case hardened carrier's bearings in production axles in February 2012.

The change to new bearings will impact service kits in a variety of ways. The part number changes have been outlined below to minimize any potential mixing of bearing parts from different suppliers.

- Bearings are manufactured and used in sets to maximize full life of the product
- NOT using SPECIFIED bearings in Dana carriers can create potential noise issues or lead to premature bearing failures and affect the warranty of product
- Mixing of bearing cups and cones can create potential noise issues or lead to premature bearing failures
- New and Old bearing cones and cups are manufactured by different suppliers
- Superseding OLD individual part numbers directly to the NEW individual part numbers could lead to mixing
  of parts that could lead to potential failures. DO NOT MIX CONES AND CUPS MANUFACURED BY
  DIFFERENT SUPPLIERS
- Spicer® service kit contents will always contain mating cones and cups

# SPICER® GENUINE BEARING KITS:

- o Service kit bill of material changes will be done on a running basis.
- o The bill of materials will begin changing in late May 2012.

Dana Part-No.	Description	Model	Ratios
514011	Bearing Kit	D170D	all ratios
514012	Bearing Kit	D190, D190D, D590, D590D	all ratios
514238	Bearing Kit	D170	all ratios
514013	Bearing Kit	R170, S170	ratios 2.69-3.91
514014	Bearing Kit	R170, S170	ratios 4.10-7.17
514015	Bearing Kit	R170D, S170D	ratios 2.53-3.91
514015	Bearing Kit	R190, R190D, S190, S190D	ratios 2.53-4.78
514016	Bearing Kit	R190, R190D, S190, S190D	ratios 5.25-7.83
514240	Bearing Kit	R170D, S170D	ratios 4.10-7.17

D AXLE INFC



## **INDIVIDUAL BEARINGS:**

- o Individual bearings cones and cups are sold separately thru service.
- Always use and install as matched sets, as noted below.
- When stock of the individual original bearing part numbers are exhausted, the part is No Longer Available.
- Customers to reference the content of this bulletin and the chart below to help ensure bearing cones/cups from the same supplier are purchased and used together.

Dana Part-No.	Description	Replaced By	Bearing Parts Matched by Location
131050-nla	Bearing Cone	139968	Pinion Bearing - Inner
131051-nla	Bearing Cup	139969	Pinion Bearing - Inner/Outer
131052-nla	Bearing Cone	139970	Pinion Bearing - Outer
131202-nla	Bearing Cone	139971	Pinion Bearing - Outer
131203-nla	Bearing Cup	139972	Pinion Bearing - Outer
131205-nla	Bearing Cone	139973	Input Shaft Cone
131206-nla	Bearing Cup	139974	Input Shaft Cup
131208-nla	Bearing Cone	139975	Output Side Gear Cone
131209-nla	Bearing Cup	139976	Output Side Gear Cup
131211-nla	Bearing Cone	139977	Output Shaft Cone
131212-nla	Bearing Cup	139978	Output Shaft Cup

### **INPUT ADJUSTER & CUP ASSY:**

- Kits 514356 and 514357, that contain the Input Adjuster & Cup Assy., will be superseded by new service kit part numbers, 504066 and 504067
- The new replacement kits will now contain the new Input Adjuster & Cup Assy's and the matching Input Bearing Cone.

Dana Part-No.	Description	Replacement Information
131205-nla	Bearing Cone	Replaced by new 139973
131685-nla	Input Adjuster & Cup Assy	Replaced by new 134354
514356-nla	Kit – Input Adjuster & Cover D190	Replaced by new 504066
514357-nla	Kit – Input Adjuster & Cover D170	Replaced by new 504067

Part-No Desc	514356 Kit - D190 Piloted I/P Cover	
Part-No.	Description	Qty
131687	cover - diff carrier	1
131692	stud	1
131374	capscrew - hex	12
131693	nut - hex	1
131685	input adjuster & cup assy	1

Part-No	514357	
Desc	Kit - D170 Piloted I/P Cover	
Part-No.	Description	Qty
131686	cover - diff carrier	1
131692	stud	1
131374	capscrew - hex	10
131693	nut - hex	1
131685	input adjuster & cup assy	1

Part-No 504067 Desc Kit - Cvr and Input Adjuster D170		
Part-No.	Description	Qty
131686	cover - diff carrier	1
131692	stud	1
131374	capscrew - hex	10
131693	nut - hex	1
134354	input adjuster & cup assy	1
139973	brg cone	1

Part-No	Part-No 504066	
Desc Kit - Cvr and Input Adjuster D190		
Part-No.	Description	Qty
131687	cover - diff carrier	1
131692	stud	1
131374	capscrew - hex	12
131693	nut - hex	1
134354	input adjuster & cup assy	1
139973	bra cone	1



### **OUTPUT SIDE GEAR AND LUBE PUMP PARTS:**

- 513876 Lube Pump Parts Kit contains the patented On Demand Lube Pump, the output side gear, spring pin, and the output side gear bearing cone.
- Bearing cone 131208 and the mating cup 131209 are being discontinued and are replaced by 139975 bearing cone and matching 139976 cup.
- 513876 will be superseded by 504065 Lube Pump and O/P Side Gear kit. <u>The new kit will not include a "bearing cone"</u>.
- When a replacement output shaft side gear bearing cone and its matching cup is required, customers to purchase individually, as needed, to assure they are using matching parts.

Dana Part-No.	Description	Replacement Information
513876-nla	Kit-Lube Pump Parts	Replaced by new 504065*
131208-nla	Bearing Cone	Replaced by new 139975
131209-nla	Bearing Cup	Replaced by new 139976

Part-No Desc	513876 Kit - Lube Pump Parts	
Part-No.	Description	Qty
131208	bearing cone	1
131368	lube pump	1
131466	output side gear	1
131541	spring pin	1

Part-No Desc	504065 Kit - OP Gear and Lube Pump	
Part-No.	Description	Qty
131368	lube pump	1
131466	output side gear	1
131541	spring pin	1

<sup>\*</sup>The New 504065 kit does not come with output shaft side gear bearing cone. Purchase separately.

## **OUTPUT SHAFT SECTION:**

- Individual output shaft bearing cones and cups are being replaced, see below for details
- o Service kit bill of material changes will be done on a running basis.

Dana Part-No.	Description	Replacement Information
131211	Bearing Cone	Replaced by new 139977
131212	Bearing Cup	Replaced by new 139978
504054	Kit – D Hsg Repair	D170 models
504060	Kit – Output Shaft Bearing	D170, D190 models AFTER Nov 2011
504061	Kit – Hsg Cover and Brg Parts	D190 models
513877	Kit – Output Shaft Bearing	D170, D190 models BEFORE Nov 2011
514352	Kit – Hsg Repair D170	D170

**Note:** Important Axle housing and output shaft bearing part changes were made in November 2011. Refer to Dana bulletin HAXL-TEC-11.1 for details regarding those parts and kits.

As always, your continued business and support of Genuine Spicer® products is appreciated!

Bernie Powers Product Manager

Benin & Fa

Spicer® Heavy Axle Products